

Annual Drinking Water Quality Report



Brook Drive Water Assn MT0000099

Annual Water Quality Report for the period of January 1 to December 31, 2024

This report is intended to provide you with important information about your drinking water and the efforts made by the water system to provide safe drinking water.

For more information regarding this report please contact Tina Malkuch at Safewater Testing Simplified, Inc., 1500 Airport Road, Kalispell, MT 59901 at 406 253 5301.

Public Participation Opportunities: We want you to be informed about your water system. If you want to learn more, please attend your annual meeting, which is announced by letter in your water bill each year. Announcements are sent one month in advance of the annual meeting with date, time and location.

Sources of Drinking Water

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the EPAs Safe Drinking Water Hotline at (800) 426-4791.

Contaminants that may be present in source water include:

- Microbial contaminants, such as virúses and bacteria, which may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.
- Inorganic contaminants, such as salts and metals, which can be naturally occurring or result from urban stormwater runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.
- Pesticides and herbicides, which may come from a variety of sources such as agriculture, urban stormwater runoff, and residential uses.
- Organic chemical contaminants, including synthetic and volatile organic chemicals, which are by-products of industrial processes and petroleum production, and can also come from gas stations, urban stormwater runoff, and septic systems.
- Radioactive contaminants, which can be naturally occurring or be the result of oil and gas production and mining activities.

In order to ensure that tap water is safe to drink, EPA prescribes regulations that limit the number of certain contaminants in water provided by public water systems. FDA regulations establish limits for contaminants in bottled water which must provide the same protection for public health.

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly and infants can be particularly at risk from infections. These people should seek advice about drinking water from their healthcare providers. EPA/CDC guidelines on appropriate means to lessen the risk of infection by Cryptosporidium and other microbial contaminants are available from the Safe Drinking Water Hotline (800-426-4791).

If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. We are responsible for providing high-quality drinking water, but we cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure are available from the Safe Drinking Water Hotline or at http://www.epa.gov/safewater/lead.

Source Water Information for Brook Drive Water Assn

which is classified as a Ground Water system

The source water assessment report for your water system provides additional information on your source water's susceptibility to contamination. To access this report please go to: https://deq.mt.gov/water/Programs/dw-sourcewater

On the webpage look under "4. Make Results of the Delineation and Assessment Available to the Public" and then click on the grey box called "Review Source Water Assessment Reports".

Brook Drive Water Assn utilizes the listed water sources below:

| Water Source Name | Water Source Type |
|------------------------|-------------------|
| WELL 1 1968 GWIC 82842 | Well |

Your water source is a 193 foot drilled well located at the north end of Big Sky Boulevard in the northeast corner of the east lot. The well was drilled in April of 1968 (GWIC 82842) through mostly glacial materials and brown sand. The water is drawn through perforation from 180 feet to 192 feet in 7 inch outside diameter 20 pound casing. The static water level varies between 60 feet and 51 feet. The water main is 950 lineal feet of 4 inch asbestos cement pipe. All service connections are composed of 3/4 inch split off a 1 inch copper lead pipe. There are 12 pressure tanks that operate between 40-60 psi. Brook Drive Water Association has one water right. You have 16 service connections, and 17 lots or 16 homes.

Water Quality Test Results Definitions

Definitions: The following tables contain scientific terms and measures, some of which may require explanation.

Action Level: The concentration of a contaminant which, if exceeded, triggers treatment or other requirements that a water system must follow.

Avg: Regulatory compliance with some MCLs is based on running an annual average of monthly samples.

Level 1 Assessment: A Level 1 assessment is a study of the water system to identify potential problems and determine (if possible) why total coliform bacteria have been found in our water system.

Level 2 Assessment: A Level 2 assessment is a very detailed study of the water system to identify potential problems and determine (if possible) why an E. coli MCL violation has occurred and/or why total coliform bacteria have been found in our water system on multiple occasions.

Maximum Contaminant Level or MCL: The highest level of contaminant that is allowed in drinking water. MCLs are set as close to the MCLGs as feasible using the best available treatment technology.

Maximum Contaminant Level Goal or MCLG: The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.

Maximum residual disinfectant level or MRDL: The highest level of disinfectant allowed in drinking water. There is convincing evidence that the addition of a disinfectant is necessary for the control of microbial contaminants.

Maximum residual disinfectant level goal or MRDLG: The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.

N/A: Not applicable.

ND: Not detectable at testing limit.

Nephelometric Turbidity Unit (NTU) – Measure of the clarity or cloudiness of water. Turbidity more than 5 NTU is just noticeable to the typical person.

Picocuries per liter (pCi/L) – Measure of the radioactivity in water.

ppb: micrograms per liter or parts per billion - or one ounce in 7,350,000 gallons of water.

ppm: milligrams per liter or parts per million - or one ounce in 7,350 gallons of water.

Secondary Maximum Contaminant Level (SMCL): SMCLs are established as guidelines to assist public water systems in managing their drinking water for aesthetic considerations, such as taste, color, and odor. These contaminants are not considered to present a risk to human health at the SMCL.

Treatment Technique or TT: A required process intended to reduce the level of a contaminant in drinking water.

The State of Montana DEQ requires us to monitor for certain contaminants less than once per year because the concentrations of these contaminants are not expected to vary significantly from year to year, or the system is not considered vulnerable to this type of contamination. Therefore, some of our data, though representative, may be more than one-year-old.

| | | | | | Lead and | Coppe | r | |
|--------------------|-----------------|------|----------------------|--------------------|--------------------|-------|-----------|---|
| Lead and Copper | Date Sampled | MCLG | Action Level (AL) | 90th Percentile | # Sites Over AL | Units | Violation | Likely Source of Contamination |
| Copper | 2023 | 1.3 | 1.3 | 0.1 | 0 | ppm | N | Erosion of natural deposits; Leaching from wood preservatives; Corrosion of household plumbing systems. |
| Lead | 2023 | 0 | 15 | 1 | 0 | ppb | N | Corrosion of household plumbing systems; Erosion of natural deposits. |

| Lead | 2023 0 | 15 | 1 | 0 ppb | N | Co | | ousehold plumbing systems; n of natural deposits. |
|--------------------------------------|---------------|----------------------------------|--------------------|---------------|-----------|---------|-----------|--|
| | | | Regula | ted Contam | inants | | | |
| | | Co | ntaminant Gr | oup: Inorgani | c Contam | inants | | |
| Regulated Contaminants | Collection Ye | Highest ar Level Detected | Range of Levels | MCLG | MCL | Units | Violation | Likely Source of Contamination |
| Barium | 2022 | 0.07 | .0707 | 2 | 2 | ppm | N | Discharge of drilling wastes; Discharge from metal refineries; Erosion of natural deposits. |
| Fluoride | 2022 | 0.15 | .1515 | 4 | 4 | ppm | N | Erosion of natural deposits; Water additive which promotes strong teeth; Discharge from fertilizer and aluminum factories. |
| Nitrate [measured as Nitrogen] | 2024 | 0.48 | .4848 | 10 | 10 | ppm | N | Runoff from fertilizer use; Leaching from septic tanks, sewage; Erosion of natural deposits. |
| | | Cor | ntaminant Gro | up: Radioacti | ve Contar | minants | | |
| Regulated Contaminants | Collection Ye | Highest ar Level Detected | Range of Levels | MCLG | MCL | Units | Violation | Likely Source of Contamination |
| Uranium | 2021 | 1.8 | 1.8 - 1.8 | 0 | 30 | ppb | N | Erosion of natural deposits. |
| | | Co | ntaminant Gro | oup: Seconda | ry Contan | ninants | | |
| Regulated Contaminants | Collection Ye | Highest ear Level Detected | Range of Levels | SMC | CL | Units | Violation | Likely Source of Contamination and or Reason for Monitoring |
| Manganese | 2023 | 5 | 0-5 | 50 |) | ppb | N | Natural sources as well as discharges from industrial uses |

Water may naturally have manganese and, when concentrations are greater than 50 ppb, the water may be discolored and taste bad. Over a lifetime, the EPA recommends that people drink water with manganese levels less than 300 ppb and over the short term, EPA recommends that people limit their consumption of water with levels over 1000 ppb, primarily due to concerns about possible neurological effects. Children younger than one year old should not be given water with manganese concentrations over 300 ppb, nor should formula for infants be made with that water for more than a total of 10 days throughout the year.

Your water system meets or exceeds all established state and federal standards.

Tina Malkuch Safewater Testing Simplified, Inc. (STS) 1500 Airport Road, Kalispell, MT 59901

Phone: 406-253-5301

email sts2535301@gmail.com

www.stsmontana.com

| PWSIO | Street Address | Apartmen 1/Unit Number | Town | State | Zipcod e | County | tead Con nect or Pre- ent | Sid | ust is the Street le Service Line Material? | Was the Street Side Mater ial Ever Lead? | Street Side Service Line Instalation Date | Building Side Service Line Material | Building Side Service Line Installation Date | How did you determine the Service Line Material? | Sorvice Line Material Committee | Service Line Classifica tion | Who Owns the Service Line? | Indicat # Service Line Diame ter | General Comments | What Type of Building? | Is there Water Treatment in the Building? | What is the Building Plumbing Material? | What was the Building Plumbing Installation date? |
|------------|-----------------|------------------------------|-----------|-------|-------------|----------|--|-------|---|---|--|---|---|---|--|---------------------------------------|----------------------------------|---|--|-------------------------|---|--|---|
| MT0000099 | 24 Big Sky BLVD | Lot 8 | Kalispeli | TM | 59901 | Flathead | No | Non L | lead -Copper | No | 1960-1969 | Non Lead - Plastic | 2000-current | Installation record | | | Combination | 0.75 | | Single Family Residence | No | Non Lead - Plastic | >2014 |
| MT0000099 | 32 Big Sky SLVD | Lot 23 | Kafispeli | MIT | 59901 | Flathead | No | Non L | nad - Copper | Na | 1960-1969 | Non Lead - Other | 1970-1979 | Installation record | | Non-lead | Combination | 1 | | Single Family Residence | Yes | Non Lead - Copper | 1960 1987 |
| MT00000099 | 33 Big Sky BLVD | Lot 10 | Kalispeli | (MT | 59901 | Flathnad | No | Non L | ead - Copper | No | 1960-1969 | Non Lead - Other | 2000 current | Installation record | | Non-lead | Combination | 1 | | Single Family Residence | Unknown | Non Lead - Other | >2014 |
| MT0000099 | 39 Sig Sky BLVD | Let 11 | Kalispell | MIT | 59901 | Rathead | No | Non L | ead - Copper | No | 1960-1969 | Non Lead - Capper | 1970-1979 | Installation record | | | Combination | 1 | | Single Family Residence | No | Non Lead - Copper | 1960-1987 |
| MT9000099 | 40 Big Sky BLVD | Lot 22 | Kalispeli | MT | 59901 | Flathead | No | Non b | ead - Copper | No | 1960-1969 | Non Lead - Copper | 1970-1979 | Installation record | | Non-lead | Combination | 1 | | Single Family Residence | Yes | Non Lead - Cupper | 1960-1987 |
| MT00000999 | 41 Bla Sky BLVD | Lot 22 | Kallsgell | MIT | 59901 | Flathead | No | Non L | ead - Copper | No | 1960-1969 | Non Lead - Plastic | 1970-1979 | Installation record | Building side determined from home owner response and picture | Non-lead | Combination | 1 | | Single Family Residence | Yes | Non Lead - Copper | 1960-1987 |
| MT0000099 | 48 Big Sky 8LVO | 1 ot 21 | Kalispell | 145 | 59901 | Flathead | No | Non t | ead - Copper | 190 | 1960-1969 | Non Lead - Plastic | 1970-1979 | Installation record | Home owner states service line 1.5" on questionairre | Non-lead | Combination | 1 | | Single Family Residence | No | Non Lead - Plastic | 1960-1987 |
| MT0000099 | 111 Brook Of | lot 13 | Kalispell | MT | 59901 | Flathead | No | Non t | ead - Copper | No | 1960-1969 | Non Lead - Copper | 1970-1979 | Installation record | Building side determined from home owner response to questionnaire | Non-lead | Combination | 1 | Home owner did not answer Building plumbing material question on questionnaire | Single Family Residence | Yes | unknown | 1960-1987 |
| | 133 Brook DR | Lot 14 | Kalismeli | MT | 59901 | Flethead | No | Non t | ead - Copper | No | 1960-1969 | Non Lead - Copper | 1970-1979 | installation record | Building side determined by home owner response and pictures provided. 3/4° diameter | Non-lead | Combination | 1 | | Single Family Residence | No | Non Lead - Copper | 1960-1987 |
| | 140 Brook DR | Let 30 | Kalicnell | MT | 59901 | Fiathead | No | Non t | ead - Conner | No | 1960-1969 | Nos Lead - Cooper | 1970-1979 | installation record | Building side determined from home owner response | Non-lead | Combination | 1 | Building plumbing combination of copper and pex | Single Family Residence | Yes | Non Lead - Other | 1960-1987 |
| MT0000099 | 145 Brook DR | 1et 15 | Kalimeli | MT | 59901 | Flathead | No | Non t | ead - Copper | No | 1960-1969 | Non Lead - Copper | 1970-1979 | Installation record | Building side determined from home owner response to questionnaire | Non-lead | Combination | 1 | Building plumbing combination of copper and pex | Single Family Residence | Yes | Non Lead - Other | 1960-1987 |
| | | Let 16 17 | Kašsneli | MET | 59901 | Flathead | No | Non 1 | and Cooper | No | 1950-1969 | Non Lead - Cooper | 1970-1979 | Installation record | Building side determined from home owner response to questionnaire | | Combination | 1 | Home owner circled all responses on home building plumbing material on questionairre - including | Single Family Residence | Yes | Non Lead - Hastic | 1960-1987 |
| | | Lat 10 | V-Servell | NAT . | 59901 | Elwhead | No | Non L | and - Conner | No | 1960-1969 | The second of the second | 1 | Installation record | No building side - varient lot | 1 | Combination | 1 | Vacant - No Dwelling | | 1 | | |
| MT0000099 | 169 Brook DR | lot 18 | Kalispeli | MIT | 59901 | Rathead | No | Non t | ead - Copper | No | | Non Lead - Coaper | 1950-1969 | Installation record | Building side determined from picture sent in by home owner | Non-lead | Combination | 1 | | Single Family Residence | No | Non Lead - Copper | 1960-1987 |

| March | Marc

IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER

Asbestos Monitoring Waiver - Effective 1/1/23-12/31/2028

know why we are not sampling for asbestos. Brook (In the Water Assn.

PWID * MTOCCOP9

Our water system has been granted a waiver for asbestos sampling. As our customers you have a right to know who was are a second of the control of the contro

based on our certification that there is no asbestos concrete pipe in the distribution system. will not conduct monitoring for asbestos because we have been granted a waiver by NEQ. This waiver is regular monitoring are an indicator of that the drinking water has or has not met hedth standards. We We are required to monitor your drinking water for specific contaminants on a regular basis. Results of

schools, and businesses). You can do this by posting this notice in a public place or distributing may not have received this notice directly (for example, people in apartments, nursinghones, copies by hand or mail. Please share this information with all the other people who drink this water, especially those who

Date and Method Distributed: Ochokur 10th 2024/sent w/milionice to be distributed What The Moth

Date signed-copy sent to DEQ/PWS: __

* Will be included in CCR 2024